

# CERTIFICATE OF COMPLIANCE

**Certificate Number** S36319  
**Report Reference** S36319-20210316  
**Date** 2021-March-17

**Issued to:** COMMSCOPE INC OF NORTH CAROLINA  
501 SHENANDOAH DR  
SHAKOPEE MN, 55379 US

**This is to certify that  
representative samples of**

IN-BUILDING TWO-WAY EMERGENCY RADIO  
COMMUNICATION ENHANCEMENT SYSTEMS

See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the  
Standard(s) indicated on this Certificate.

**Standard(s) for Safety:**

ANSI/CAN/UL 2524, In-building 2-Way Emergency Radio  
Communication Enhancement Systems


**Additional Information:**

See the UL Online Certifications Directory at  
<https://iq.ulprospector.com> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>




# CERTIFICATE OF COMPLIANCE

**Certificate Number** S36319  
**Report Reference** S36319-20210316  
**Date** 2021-March-17

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

USL - In-building Two-way Emergency Radio Enhancement System Equipment:

Bi-directional Amplifiers, ID No. 7831758-0001, 7831758-0011, 7831758-0012, 7831758-0013, 7831758-0014, 7831758-0002, 7831758-0021, 7831758-0022, 7831758-0023, 7831758-0024, 7831851-0001, 7831851-0011, 7831851-0012, 7831851-0013, 7831851-0014, 7831851-0002, 7831851-0021, 7831851-0022, 7831851-0023, 7831851-0024.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

